

FPH-200/300/400/500W MODEL

COIL WRAPPING MACHINE

OPERATION MANUAL



FPH-200/300/400/500W Coil Packing Machine

Table of Contents

I. Application Note	3
II.Important Alert	3
III. Technical Parameter	4
IV. Machine Installation	5
V. Machine Operation	6
VI. Troubleshooting	12
VII. List of Main Spare Parts	13

Reference Picture:



I. Application Note

This machine can be used to conduct relatively closed packaging for different dimensions of steel wires or coiled unpackaged objects so as to play a role of anti-rust, waterproof, dustproof, anti-damage and anti-aging etc..


The packaging material mating with this machine is of compound packaging paper tape or high-quality compound knit packing tape.

II. Important Alert

- I. Abuse will lead to serious result.
- II. Do have the machine grounded.
- III. In the event of urgent failure occurrence, do shut off or cut off power supply, and then carry out relevant troubleshooting operations after safety confirmation.
- IV. Never modify the control program and relevant parameter settings of this machine without authorization.
- V. Never tear off various signs marked on the machine.
- VI. Never open the electrical box when the machine is working.
- VII. In the case of the lifting and lowering of unpackaged object, do ensure safe, steady and orderly operation, and unpackaged object's collision with the machine shall be strictly forbidden.
- VIII. Do Uninterrupted monitoring by operator when the machine is

working. Avoid packing object deflection at wrapping process.

III. Technical Parameter



Model	FPH-200W	FPH-300W	FPH-400W	FPH-500W
Coil OD	500-800mm	600-900mm	800-1000mm	800-1200mm
Coil ID	200-600mm	250-800mm	500-650mm	500-800mm
Coil width	30-200mm	80-300mm	100-400mm	150-500mm
Coil weight	5-50kg	5-80kg	10-100kg	20-200kg
Roller speed	2-4m/min	2-4m/min	2-4m/min	2-4m/min
Rotating speed	40-120 r/min	40-110 r/min	40-90 r/min	40-70 r/min

Wrapping				LLDPE/PE/Stretch
material	film/PVC/	film/PVC/	film/PVC/	film/PVC/
Material width	70mm	90mm	100mm	120mm
Material OD	80-120mm	80-120mm	80-120mm	120-200mm
Material ID	55mm	55mm	55mm	55mm
Power output	App. 1.2kw	App. 1.2kw	App. 1.8kw	App. 2.0kw
Power voltage	380V/50Hz	380V/50Hz	380V/50Hz	380V/50Hz
Wrapping speed	15-20sec/pcs	15-20sec/pcs	15-20sec/pcs	15-20sec/pcs
Overlapping rate	20%-90%	20%-90%	20%-90%	20%-90%

IV. Machine Installation

1. This machine is composed of main engine, cutter/tape wheel support and electrical box, etc.

2. Place the main machine on the ground surface horizontally and then assemble the above-mentioned spare parts at proper position. And then install some small auxiliaries.

3. Prevent against the occurrence of bruise, compression injury, crushing injury, contusion and other accidents during the installation.

4. As the machine has been transported and moved, all flexible shall be inspected carefully.

5. The entire installation shall be completed under the condition that the power supply is cut off.

6. The machine shall be mounted on flat and hard ground, where the ground load should be more than $1t/m^2$. The power supply should be in www.fhopepack.com

accordance with written in the nameplate.

7. Only trained personnel can be allowed to enter the installation site.

8. Next working procedure can be executed only after all the installation operations are completed.

9. The machine shall be mounted in dry and dust free environment.

V. Machine operation

1) Introduction to operating panel and switch function:

POWER: The main switch of machine power supply which is used to connect or shut off the machine power supply.

EMERGENCY STOP: The control switch which is used to control circuit. Press this switch to shut down the whole machine in the case of emergency.

MANUAL/AUTO: The working mode of this machine is classified into manual operating mode and automatic operating mode. "MANUAL" mode is generally used for inspection, adjustment, troubleshooting and specific conditions. In normal operation conditions, "AUTO" mode is adopted. RING START: It is usually used as startup button in "AUTO" mode. Press the button to make the ring work in "Manual"mode.

RING STOP: It is used to stop the machine in "AUTO" mode. Press the button to make the ring stopped in "MANUAL" mode.

RING RESET: It is used to have the ring reset. This button is operated in both "AUTO" and "MANUAL" mode.

RING DOTTING: It is used to have the ring run slowly in "MANUAL" and "AUTO" modes.And ensure ring can get through the center of the packing object.

CUTTER: It is used to cut the packaging tape. It is operated in both "AUTO" and "MANUAL" mode

ROLLER RUNNING (ANTICLOCKWISE/CLOCKWISE) : It shall be used to put the roller under clockwise or anticlockwise under running status when "MANUAL" mode is selected. The switch is invalid in "AUTO" mode & it shall be under "OFF" status in "AUTO" mode.

Cylinder Fwd. : Object be hoisted and come out from working position. Cylinder Rev.: Device withdraws for putting packing object in working position.

2).Introduction to Main Content of HMI

1. "WRAPPING MODE" setting page



Note:

Ring speed: It decides to the running Frequency of the running ring.Range:0-60Hz

Roller speed: It decides to the running Frequency of the running roller.

Range: 0-60Hz


Superposition: It displays the overlap rate of the packing tape.

Note: After "Ring Speed" and "Superposition" set, "Roller speed" wills automatic generation. Therefore "Roller speed" is just a display number.

"Twist degree": "1" means packing finished once.

"2" means packing be divided into two times. This situation need packing two times when width and diameter of unpacked is large, packing tape on storing wheel is not enough for once packing.

1. Wrapping Mode



Note: • "Ring speed" and "Roller speed" not only define the running speed of ring and roller respectively, but are also in connection with the overlapping of packaging tape. The two setting parameters can be set by touching. If the ring speed is high and roller speed is low, the packaging tape features a large overlapping range; on the

contrary, the overlapping range is small.

2. Parameter setting

Poster	0	0	0	0	FI
	物体外径 outer dia.	物体内径 inner dia.	物体厚度 ply	皮带周长 strap length	F 2
	0.0	0.0	0.0	0.0	E
	定位系数 orientation parameter	转环定位时间 ring orientation time	托辊定位时间 roller orientation time] 切断时间 shear time	E
			迈	回 return	STS

OD	Range 0~1100	As requirement,Unit/mm
ID	Range 0~1000	As requirement,Unit/mm
Width	Range 0~450	As requirement,Unit/mm
Strap perimeter		Been setted before leave factory,Unit/mm
Location Coefficient	Range-9~9	PLC can cut down packing tape automaticly. This parameter should be modify as specific element, such as diamension of object, Stretching coefficient of packing tape
Ring Location Time	Range 0~20	That's the subsequent rotational time after basic ring action done for ensuring packing tape exhausted on the tape storage wheel.
Suppotive roller Location Time	Range 0~20	That's the subsequent rotational time after baisc action of suppotive roller done for adhesive packing material in right position.

Cutting Time	Range 0.1~3	Time of cut down packing tape
--------------	-------------	-------------------------------

3).Operation

- 1. Rotate the "POWER" switch clockwise to connect to the power supply of the machine.
- 2. Rotate the "EMERGENCY STOP" switch clockwise. At this time, the indicator lamp on the top of electrical box is"on".
- Turn the "MANUAL/AUTO" switch on the operating panel to "AUTO" position, and then the machine will work in automatic mode. Operate HMI, select and set the options one by one and make confirmation.
- 4. Put packing object on the center of working position.
- 5. Operate the "RING DOTTING" button to have ring running slowly. Ensure the ring can position at the center or smoothly thread through the inner diameter of unpackaged object. If the deviation is too much, the "BASE BOARD UP" or "BASE BOARD DOWN" button can be operated to adjust the horizontal level of ring.
- 6. Operate the PROTECTIVE ROLLER manually to have the unpackaged object protected by the down protective roller effectively.
- 7. Tape-Threading and adhesive on object.
- 8. Press the "RING START" button to have the machine run in automatic manner until one complete packaging is finished.
- 9. After ring restoration, press "Cylingder Fwd" move out Packing object. Start next new packaging operation according to the above-mentioned operating process.

VI. Troubleshooting

Problem	Possible cause & solution
I. The complete machine doesn't work.	1. Check external power supply and air supply.
II. The ring doesn't rotate or rotates abnormally.	 Check the wear of friction wheel. If it is seriously worn, new friction wheel shall be replaced. Adjust the friction wheel. Check whether any packaging tape is clipped into the friction pulley track.
III. Packaging tape is too loose or tight.	1. Adjust the force of tension belt.
IV. The ring and roller don't work.	 Check power supply. Check whether the parameter values of "ring speed" and "roller speed" in the wrapping mode setting page are properly set.
V. The machine shuts down suddenly, alarm lamp flashes and HMI pops up relevant information.	1. Check corresponding motor and connecting wire according to the prompt of HMI.
VI. Packaging tape is multi-folded.	 Check whether the feeding route of packaging tape is on one straight line. Check whether the tape storing wheel on the ring is damaged. High-quality packaging tape shall be replaced. As too many tapes are stored on the tape storing wheel, "twice wrapping" shall be needed.
VII. The overlapping degree of packaging tape cannot be	1. Check whether the parameter values of "ring speed" and "roller speed" are in consistent with the value displayed on the frequency converter

adjusted.	in electrical box. If inconsistent, please check the communication line between the HMI and
	frequency converter.


VII. List of Main Spare Parts


Description	Part Number	Brand	Remark
PLC	DVP32ES00R2		
Frequency converter	Frequency converter of ring VFD037M43B Frequency converter of roller VFD007M43B	DELTA	
HMI	DOP-57GS		
Ring motor	ZL28-0.75-5S-DC24V	YK	
Roller motor	ZF-22-0.1-300S	ҮК	
cylinder	SI100x150		
Air treatment	BFC2000		
solenoid valve	4V430C-15-DC24V 4V230C-08-DC24V		
Large friction wheel	FP-H-M-D		Factory standard
Small friction wheel	FP-H-M-X		Factory standard
Tension belt	FP-H-P		Factory standard
Cutter	FP-H-D		Factory standard


FPH-200/300/400/500W Coil Packing Machine

Tape storing wheel	FP-H-L-02		Factory standard
Fuse	4A	S	Standard

Electrical diagram:







	X17	X16	X15	X14	X13	X12	X11	X10	Х7	Xe	S X5	5 X4	X3	3 X2	X1	XC
L		,	115	114	1	1	111	110	107	106	105	104	103	102	101	100
			ø	ø			ø	ø	ø	ø	Ø	ø	ø	ø	ø	ø
			115	114			111	110	107	106	105	104	103	102	101	100
			2-\	τ			Ŀ	E-	E-	E-	E-	₽	E	E-\	\${	ľ
		Ç	SA3	SA2			SA1	SB7	SB6	SB5	SB4	SB3	SB2	SB1	J1	B1
1-22 ø	\$B8 Q	Running	Roller Anticlockwise	Roller Clockwise			Manual	Manual Cutter	Cylinder Rev.	Cylinder Fwd.	Ring Dotting	Manual Reset	Ring Stop	Ring Start	Ring Counts	Roller Counts

